# National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: CHI98FA119

Aircraft Registration Number: N868FE

Occurrence Date: 04/07/1998

Most Critical Injury: Fatal

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
BISMARCK	ND	58504	0838	CDT	
Airport Proximity: Off Airport/Airstrip	Distance From	m Landing Facility:	1	Direction Fro	m Airport: 128

Aircraft Information Summary

· · · · · · · · · · · · · · · · · · ·		
Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	208B	Airplane

Sightseeing Flight: No

# Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF FLIGHT

On April 7, 1998, at 0838 central daylight time (cdt), a Cessna 208B, N868FE, registered to Federal Express Corporation, and operated by Corporate Air, of Billings, Montana, as FedEx Flight 8738, was destroyed following a loss of control and collision with the terrain. The airplane was on the ILS approach to Runway 31 at the Bismarck Municipal Airport, Bismarck, North Dakota, when the accident occurred. The commercial pilot received fatal injuries. The 14 CFR Part 135 flight was operating on an IFR flight plan. Instrument meteorological conditions prevailed.

The flight departed Grand Forks, North Dakota, at 0728 cdt, with 2,710 pounds of cargo on a regular scheduled flight to Bismarck. Two other Corporate Air flights, also being operated as FedEx cargo flights, departed Grand Forks shortly after N868FE. Both of these airplanes were destined for Bismarck.

N868FE was cleared to climb to 6,000 feet mean sea level (msl) after takeoff from Grand Forks. Shortly after takeoff the pilot requested a climb to 8,000 feet msl due to icing. The pilot was issued a climb to 7,000 feet msl. N868FE then contacted Minneapolis Air Route Traffic Control Center and stated to the controller that he was not picking up any more ice at 7,000 feet msl and that he was on top of the clouds. The pilot informed the controller that the ice he had picked up was mixed and that it was like wet droplets running back over the wing and freezing.

The pilot of N868FE was instructed to contact Bismarck Approach Control who issued vectors and cleared N868FE for the ILS Runway 31 approach. The pilot then contacted the Bismarck Air Traffic Control Tower and was cleared to land at 0836 cdt. The pilot acknowledged the clearance at 0837 cdt. There was no further radio contact with the N868FE.

### PERSONNEL INFORMATION

The pilot was born December 6, 1956. He was the holder of a commercial pilot certificate with single, multi-engine, and instrument ratings. He also held a second class medical issued on November 14, 1997. The medical certificate contained the limitation that the holder shall wear corrective lenses.

A review of the pilot's last logbook revealed his most recent biennial flight review was on December 24, 1997. He had accumulated a total of 2,265 hours of flight time, 18.9 hours of which were in a Cessna 208B airplane at the time of the accident.

The pilot had 1.9 hours of actual instrument time in a Cessna 208 and 4.7 hours of simulated instrument time in a Cessna 208.

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

Occurrence Type: Accident

Narrative (Continued)

The pilot completed the Flight Safety International Caravan I Initial Pilot Training Course on March 27, 1998.

AIRCRAFT INFORMATION

N868FE was a Cessna 208B, serial number 208B0193. The airplane had accumulated 6,140 hours of time in service at the time of the accident. The engine also had 6,140 hours of total time at the time of the accident. The most recent inspection was conducted on February 26, 1998, 45 hours prior to the accident.

### METEOROLOGICAL INFORMATION

Another Corporate Air pilot departed Grand Forks approximately 5 to 10 minutes after N868FE. His destination was also Bismarck. He stated both flights had filed to fly at 6,000 feet msl. He stated he was cleared to 8,000 feet msl after departure for separation purposes. He reported the tops were at 6,700 feet msl with light mixed icing in the clouds which accumulated to 1/8 to 1/4 inch. He reported hearing the pilot of N868FE request a higher altitude because he was picking up ice at 6,000 feet msl. He stated the pilot of N868FE was cleared to 7,000 feet msl. He recalled center asking the pilot of N868FE if he was out of the ice. The pilot reported that he was now on top and that he had been picking up light mixed ice in the clouds and that some of it was running back and freezing aft on the wing. This pilot stated that en route the tops lowered to about 4,000 feet msl and he was clear of the clouds until he began the descent into Bismarck. He stated he encountered light mixed ice during the approach into Bismarck which had accumulated 1/8 to 1/4 inch. He stated he recalled the ice melting away during the ILS approach.

A third Corporate Air pilot was also flying from Grand Forks to Bismarck around the same time. He stated he also picked up light mixed ice during the departure from Grank Forks so he requested a higher altitude and was subsequently cleared to 8,000 feet msl. He stated that at 7,000 feet msl he was out of the icing conditions, but was still in instrument conditions. By 8,000 feet msl he was between layers. Approximately 35 miles northeast of Bismarck his "...flight conditions deteriorated." He was in instrument conditions at 8,000 feet msl and began picking up light clear/mixed icing during the descent through 7,600 feet msl. He reported he continued to pick up ice through 5,000 feet msl and as he descended through 4,000 feet msl the ice began to melt. He stated that after landing he noted the unprotected areas of his airplane had 3/8 to 1/2 inch of ice on them and the protected areas had approximately 1/4 in of ice. The pilot landed at 0850 cdt.

A pilot, flying a Cessna T210, who departed from Bismarck an hour before the accident stated the weather information forecast the chance of light to occasional moderate icing in clouds between the freezing level and 14,000 feet msl. After departure from Bismarck he encountered cloud bases at about 1,000 feet above the ground (agl) or 2,700 msl. There were several layers of clouds as he departed to the northwest. The lowest layer had a base at 3,500 msl and tops at 6,000 msl. In this layer the outside air temperature was about +2C with liquid precipitation. As the rain hit the leading edge of the wings, it moved back aft of the de-icing boots. The rain started to freeze and stick to the bottom side of both wings. The pilot reported the ice adhered to the left wing from the pitot mast inboard from approximately mid chord, aft to the end of the flaps. From the pitot mast outboard, the ice formed from the trailing edge of the de-icing boots, back to the end of the ailerons. This freezing precipitation ended about 6,000 msl. From approximately 6,000 msl to about 7,000 msl, he was still in IMC with light rime icing. The 1/4 to 1/2 inch of ice did not shed off the wings when the pilot inflated the boots. The pilot recycled the boots two or three times, but the ice remained. He could see the ribs on the boots expanded and ice flex, but the it did not shed off the leading edge of the wings.

Reported weather at Bismarck, at 0840 cdt, was an overcast ceiling at 400 feet, visibility 8 statute miles, wind was from 010 degrees at 12 knots, temperature and dewpoint were both 33 degrees F, and the altimeter was 29.85".

# National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

Occurrence Type: Accident

Narrative (Continued)

### FLIGHT RECORDERS

The airplane was equipped with a Power Analyzer and Recorder (PAR) unit which is a light weight, compact monitoring system designed to provide the airplane operator with real time performance data and a non-volatile record of engine/airframe performance. The PAR unit accumulates, stores, and outputs the records of all starts, shutdowns, limit exceedences and other specified data for engine conditions checks and trend analysis. See attached PAR Incident Investigation Report for details.

### WRECKAGE AND IMPACT INFORMATION

The NTSB on-scene investigation began at 1200 on April 8, 1998. The airplane impacted the terrain in an field approximately 1.6 miles from the end of Runway 31. The initial impact ground scar contained pieces of red lens cover from the left wing. The engine contacted the ground shortly thereafter at which point one propeller blade separated. Pieces of the right wing were located in the third ground scar, which was relatively in line with the first ground scar. The engine, cockpit, overhead panel, and the left wing separated from the fuselage shortly after this impact. The main portion of the wreckage came to rest shortly thereafter. The fuselage came to rest inverted along with the right wing and the empennage which separated from the fuselage. The distance between the first ground impact and where the main wreckage came to rest was 102 feet. The wreckage path was on a heading of 250 degrees.

### MEDICAL AND PATHOLOGICAL INFORMATION

A post mortem examination of the pilot was conducted on April 8, 1998, by the North Dakota Department of Health, Bismarck, North Dakota.

The pilot's toxicological analysis was performed by the Federal Aviation Administration's Civil Aeromedical Institute, Oklahoma City, Oklahoma. The test results were negative for those substances screened.

### TESTS AND RESEARCH

The engine was inspected and torn down at Executive Air Taxi Corp., Bismarck, North Dakota, on April 8th and 9th, 1998. See attached Engine Teardown Report for details.

The propeller was inspected at DuPage County Airport, West Chicago, Illinois, on August 7, 1998. See attached Propeller Teardown Report for details.

## ADDITIONAL DATA

Parties to the investigation were the Federal Aviation Administration, Cessna Aircraft Company, United Technologies Pratt & Whitney Canada, Federal Express Corporation, Corporate Air.

National Transportation Safety Board

FACTUAL REPORT

ANTATION

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

TACIONI				70171000									
AVIATION		Occu	rrence Ty	ence Type: Accident									
Landing Facility/Approach Inf	ormation	•											
Airport Name	Airport ID	D: Ai	rport Elevat	ion	Run	way Used	Runwa	ay Lengt	h	Runw	ay Width		
BISMARCK MUNICIPAL			BIS		1677 Ft.	MSL	31		8794			150	
Runway Surface Type: Asphalt													
Runway Surface Condition: Snow-	-wet												
Type Instrument Approach: ILS-co	mplete												
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer Cessna				odel/Seri 08B	ies					Serial 208B	Numbe 0193	r	
Airworthiness Certificate(s): Norma	al		!										
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	Homebuilt Aircraft? No Number of Seats: 2					t.		3997	LBS	Number of Engines: 1			: 1
- · · · · · · · · · · · · · · · · · · ·				Engine Manufacturer: Model/Series: P&W PT 6A-114							Rated Power: 600 HP		
- Aircraft Inspection Information													
Type of Last Inspection			Date of I	ate of Last Inspection Time Since Last Inspection					ection	Airframe Total Time			
AAIP			02/26/	1998	98 45 Ho					ours 6140 Hours			
- Emergency Locator Transmitter (E	ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No		ELT Aided in Locating Accident Site? No									
Owner/Operator Information													
Registered Aircraft Owner			Stree	et Addr	ess 3101 TCI	HUL	AHOM <i>A</i>						
FEDERAL EXPRESS CORPO	RATION		City								State	- 1	Zip Code 38118
			Stree	Street Address									
Operator of Aircraft				P.O. BOX 30998									
CORPORATE AIR, INC.			City	City BILLINGS							State MT		Zip Code 59107
Operator Does Business As: FEDE	·	Operator Designator Code: HYSA											
- Type of U.S. Certificate(s) Held:													
Air Carrier Operating Certificate(s):	On-demand Air 1	Гахі											
Operating Certificate:					Operator C	ertific	cate:						
Regulation Flight Conducted Under	: Part 135: Air Ta	xi & Co	ommuter	r									
Type of Flight Operation Conducted	: Unknown												
		FACTU	JAL RE	EPORT	- AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

AVIATION Occurrence Type: Accide						cident					
First Pilot Information											
Name					City			State	Date of Birth	Age	
On File					On File			On File	On File	41	
Sex: M Seat	Occupied:	: Left	Prir	ncipal Profes	n Pilot		Cert	tificate Nu	mber: On File		
Certificate(s):	Fligh	nt Instructor;	Commercia	al			•				
Airplane Rating(s): Multi-engine Land; Single-engine Land											
Rotorcraft/Glider/LTA: None											
Instrument Rating	Instrument Rating(s): Airplane										
Instructor Rating(s): Airplane Single-engine; Instrument Airplane											
Type Rating/Endorsement for Accident/Incident Aircraft? No  Current Biennial Flight Review?											
Medical Cert.: Cla	ass 2	Medica	al Cert. Status	s: Valid Med	dicalw/ wa	aivers/lim.		Date of La	st Medical	Exam: 11/14/19	997
- Flight Time Matr	ix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Instr Actual	ument Simulated	Rotorcra	ft Glider	Lighter Than Air
Total Time		2265	19	2247	20	456	202	5	7		
Pilot In Command(F	PIC)	2103	19								
Instructor									_		
Last 90 Days		71	19	71		24	20		5		
Last 30 Days		19	19	19		1	2	!   ;	3		
Last 24 Hours	·	1	1 <u></u>	1		<u>  1</u>	- la au a Da afa a			On a seed Dileto N	
Seatbelt Used? Y	es ———	Shou	lder Harness	Used? Yes		I OXIC	ology Perfor	mea? Yes		Second Pilot? N	0
Flight Plan/Itine											
Type of Flight Plan	n Filed: IF	R									
Departure Point						State	e Airp	Airport Identifier		arture Time	Time Zone
GRAND FORKS	3					ND	GF	GFK		8	CDT
Destination						State	e Airp	Airport Identifier			
Same as Accide	ent/Incide	ent Location					BIS	3			
Type of Clearance	≕ IFR					-	-				
Type of Airspace:	Class I	D									
Weather Inforn	nation										
Source of Briefing:  Company; Flight Service Station											
Method of Briefing:											
				FACTUAL	REPORT	- AVIATIO	N				Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

	Occurre	Occurrence Type: Accident											
Weather Information													
WOF ID	Observation Time	Time Zone	WOF Elev	istance Fro	m Accid	lent Site Direction From Accident Site							
_													
BIS	0840	CDT	1677	Ft. MSL				1 NM	1 NM 128 Deg.				
Sky/Lowes	st Cloud Condition: Unkn	iown		0 Ft. AGL Condition of I					of Ligh	Light: Dawn			
Lowest Ce	eiling: Overcast		400	Ft. AGL	Visib	oility:	8	SM	Altir	meter:	29.00	"Hg	
Temperatu	ure: 1 °C [	Dew Point:	1 °C	Wind	Direction	: 10			Density Altitude: 457				
Wind Spee	∍d: 12	Gusts:		Weat	her Condt	tions at Acc	cident Si	ite: Instrume	ent C	onditions			
Visibility (R	RVR): 0 Ft.	Visibility (	(RVV) 0	SM	Intensit	ty of Precipi	itation:	Moderate					
Restriction	ns to Visibility: None												
Type of Pre	ecipitation: Snow Sh	nower; Freezi	ng Rain										
Accident	Information												
Aircraft Dar	mage:		Aircraft F	Fire:				Aircraft Explosion					
Classificati	ion:												
- Injury Sur	mmary Matrix	Fatal	Serious M	linor	None	TOTAL			_				
First Pi	ilot	1				,	1						
Second	d Pilot												
Studen	ıt Pilot												
Flight In	Instructor						7						
Check	Pilot						7						
Flight E	Engineer						7						
Cabin /	Attendants						7						
Other C	Crew						7						
Passen	ngers						7						
- TOTAL A	ABOARD -	1					1						
Other G	Ground	0	0	0		(	ō						
- GRANE	D TOTAL -	1	0	0			1						
		·					,						

National Transportation Safety Board

# FACTUAL REPORT AVIATION

NTSB ID: CHI98FA119

Occurrence Date: 04/07/1998

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

TODD J. CARLSON

Additional Persons Participating in This Accident/Incident Investigation:

VERL W ADDISON 1801 23TH AVE N. FARGO, ND 58102

LEAH D RIDDLE ONE CESSNA BOULEVARD WICHITA, KS 67215

THOMAS A BERTHE 15 EAGLE DRIVE S. BURLINGTON, VT 05403

ROBERT D MCIVER P.O. BOX 30998 BILLINGS, MT 59107